DA

The Joint Transport Commissioner, Tripura, Agartala.

Subject: Transport Safety Certificate of O1(One) no. of vehicle to be used

in Synod Foundation English Medium School, Lefunga, West

Tripura-799210.

Ref.: No.F.5/IV/SYFEMS/LG/MNP/WT/2016-17 dated 25-11-2016.

Sir,

With reference to the subject cited above, I, Sri M. Mog, Sr. Motor Vehicle Inspector O/o the Joint Transport Commissioner, Tripura, Agartala inspected 01(One) no. of School bus of the Synod Foundation English Medium School, Lefunga, West Tripura-799210. The inspection report is given in annexure -"A".

This is for favour of your kind information.

Enclo:- As stated (01 sheet)

Yours faithfully

Sr. Motor Vehicle Inspector, O/o. Joint Transport Commissioner

Tripura: Agartala

Government of Tripura Office of the Joint Transport Commissioner Tripura: Agartala

No.F.21(33)/JTC/SB/2011/ 7352

Dated, Agartala, November 30, 2016

To

The Headmaster, Synod Foundation English Medium School, Lefunga, West Tripura-799210.

Subject: Transport Safety Certificate of O1(One) no. of vehicle to be used

in Synod Foundation English Medium School, Lefunga, West

Tripura-799210.

: No.F.5/IV/SYFEMS/LG/MNP/WT/2016-17 dated 25-11-2016.

Sir,

Please find enclosed herewith the inspection report of O1(One) no. of Mini bus & being used by your school submitted by the Sr. Motor Vehicle Inspector of the office of the undersigned.

It appears from his report that the vehicle is Road worthy.

This is for your information, please.

Enclo:- As stated (02 sheet)

Yours faithfully

Joint Transport Commissioner

Tripura : Agartala

Inspection report of mechanical check of 01(One) no. of Mini Bus to be used in Synod Foundation English Medium School, Lefunga, West Tripura, PIN-799210.

Months and	Remarks		Road worthy	
1		14	Yes	+
		13	Voe	
	Two emergency exits in the buses are found available or not. (Y/N)	12	Vari	3
	The drivers of the school buses have valid PSVBUS (Y/N)	111	Varia	3
To keep	school bogs safety, there should be a space fitted under the seats.	10	1	Yes
	School name and telephone No. No. written on the bus. (Y/N)	0		Yes
	Fire Extinguisher found in the Bus, (Y/N)	a		Yes
	The windows of bus fifted with horizontal grills. (Y/N)	1		Yes
	Bus have a First Aid Box (Y/N)	7	0	Yes
	Type of the time back and of front of inspection the bus (V/N)		0	Yes
			4	11719
			m	MINI
	Registration		2	TR01-F-3477
-	12, 5,		-	1

Sr. Motor Vehicle Inspector,
O/o the Joint Tr. Asport Commissioner,
Tripura, Agartala.